

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



Bill To
Kevin Kay



Project
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
370-350	2	Banjo Bolt	4.17	8.34T
370-650	4	Fiber washer	0.66	2.64T
Parts	1	Spare tire cover	110.00	110.00T
Parts		Chrome wire wheels/set of 4/used	521.00	521.00T
Parts	2	JA CBC1448 Grommet, Mount	0.75	1.50T
Parts	1	CO 9028 Fuel Flex Hose	52.00	52.00T
Parts	1	CO 15420 Column Cover	96.04	96.04T
UPS		UPS from XK's Unlimited	10.05	10.05
452-765	5	Inner tube 175/185 x 15	14.36	71.80T
011-881	2	Jaguar knock-off L/H	57.74	115.48T
011-880	2	Jaguar knock-off R/H	57.74	115.48T
950-075	1	Jaguar oil filter	8.75	8.75T
CAS GTX 20-50	6	Castrol GTX 20-50 Motor Oil Quart	4.59	27.54T
Parts	1	CO23772 speed hold bellows	12.92	12.92T
Parts	1	JA3736 pan gasket	9.08	9.08T
UPS		UPS	8.55	8.55
Parts		Stainless Steel exhaust system/complete	587.38	587.38T
Subcontract		Big O/mount and balance	87.50	87.50
162-770	2	Back mount spot lamp	141.95	283.90T
535-234	1	Pinion oil seal	23.50	23.50T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS

1530 CHARLES DRIVE  
REDDING, CA 96003


Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net

<b>Bill To</b>
Kevin Kay



<b>Project</b>
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
Subcontract		Walker's Plating/strip chrome parts	30.00	30.00
D52D	1	Brake pads DB4 repco deluxe.	35.95	35.95T
011-914	4	Tie rod boot	2.45	9.80T
Parts	4	CO 10996 Link Bushing	0.61	2.44T
Parts	2	CO 10940 Link Bushing	1.33	2.66T
Parts	2	CO 14983 ARB Bush	3.21	6.42T
Parts	2	CO 23549 Subframe Mount	7.05	14.10T
Parts	2	CO 9004 V Mount	23.22	46.44T
Parts	8	BD 4321 Rubber Buffer	1.46	11.68T
Parts	1	CO 10188-1 Battery Rubber	4.20	4.20T
Parts	6	BD 4951 Sedan Buffer	1.24	7.44T
Parts	2	BD 10224 Rubber Buffer	1.17	2.34T
Parts	4	GR 64932067 Wheel Cylinder	157.95	631.80T
Parts	16	06 3090 Caliper Bolt	1.56	24.96T
Parts	16	CO 726 Star Washer	0.15	2.40T
Parts	1	06 3000 Bridge Pipes	29.35	29.35T
14276	2	BCA Bearing	10.59	21.18T
282-810	1	Sealing strip	2.95	2.95T
Parts	1	CO16774 heater core	189.95	189.95T
Parts	1	18-2011 grommet	6.21	6.21T
872-800	1	Distributor cap	42.75	42.75T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



Bill To
Kevin Kay



Project
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
011-146	2	Mount	15.95	31.90T
7734	6	NGK-BPR5ES, spark plug	2.95	17.70T
872-790	1	Rotor 6 cyl	5.95	5.95T
704-1278	0.5	Spring stabilizer/small/set of 4	11.98	5.99T
09-BS/50	6	Jubilee clip 2A	3.95	23.70T
09-BS/20	16	Jubilee clip 00	3.25	52.00T
400-418	1	Bumper overrider rubber	0.00	0.00T
371-055	2	Needle and seat/Viton	11.95	23.90T
294-900	2	Float bowl gasket	0.95	1.90T
370-650	9	Fiber washer	1.10	9.90T
Parts	1	MFH117 power steering filter	14.52	14.52T
Parts	1	JA7551 o-ring	4.38	4.38T
Parts	1	CO26782 battery tray	43.06	43.06T
Parts	2	0249GRY seat belt	39.70	79.40T
Parts	1	08-1538 spark plug wires	213.64	213.64T
322-900	2	Bumper bolt	2.10	4.20T
377-036	1	Fuel pump SU double end dual polarity.	285.80	285.80T
Parts	2	377-350 fuel pump bracket	14.67	29.34T
16-0312	1	Screenjet sticker	7.89	7.89T
20030	1	Chrome l/p frame	12.95	12.95T
Parts	1	BD10370 Vent tube	26.49	26.49T
Parts	1	BD 25894 Plate Mount	11.95	11.95T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



<b>Bill To</b>
Kevin Kay



<b>Project</b>
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
Parts	1	CO18484 Radiator Cap	4.49	4.49T
Parts	1	08 1538 Assembled wires	213.64	213.64T
Parts	1	CO15949 Oil bypass hose	3.09	3.09T
Parts	1	CO24267 L/P hose	8.07	8.07T
Parts	1	CO16099	9.03	9.03T
Parts	1	CO14148/2 H/P P/S hose	96.31	96.31T
Parts	1	09 0160 Bypass stat	22.36	22.36T
Parts	1	CO8047 Coil bracket	20.42	20.42T
Parts	1	CO13681 Fuel filter	26.75	26.75T
Parts	2	CO13705 Banjo bolt	10.32	20.64T
Parts	2	03 0137 Banjo fitting	17.91	35.82T
Parts	4	CO784 Banjo washer	1.49	5.96T
Parts	2	03 8102 Damper	11.25	22.50T
Parts	2	CO2227 Breather gasket	0.90	1.80T
Parts	1	CO4985 Thermo gasket	1.55	1.55T
Parts	2	CO15587 Return Spring	1.95	3.90T
Parts	1	CO9928 O-Ring	0.76	0.76T
Parts	1	CO15727 Heater Pipe	38.16	38.16T
Parts	1	CO20764 Drop link	19.14	19.14T
Parts	2	CO10996 Link bushing	0.61	1.22T
Parts	2	CO11047 Spacer tube	4.02	8.04T
Parts	2	CO11045 Washer	2.33	4.66T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



<b>Bill To</b>
Kevin Kay



<b>Project</b>
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
Parts	1	10 FHW1272-22 Heater valve	70.81	70.81T
Parts	1	CO23601 Fuel cap	35.46	35.46T
Parts	1	LU52477 Map lamp	15.95	15.95T
Parts	1	16 3754 Insulation	73.95	73.95T
Parts	2	16 2600 Screw kit	3.96	7.92T
Parts	1	09 1415 Hose kit	64.64	64.64T
Parts	1	BD5366-1 Chrome Joint	4.04	4.04T
Parts	1	BD17065 Ashtray	20.50	20.50T
Parts	1	CO22272 Horn button	45.48	45.48T
Parts	4	CO 4928 Jack plug	5.68	22.72T
Parts	1	BD 4920/3 Bonnet rubber	15.29	15.29T
Parts	2	BD 18080/1 Bumper end pair	21.32	42.64T
Parts	1	CO16486 Aircleaner seal	21.91	21.91T
Parts	1	CO16483 Base gasket	14.11	14.11T
Parts	1	CO16484 Air filter	27.48	27.48T
Parts	1	CO16492 A/C wingnut	4.46	4.46T
Parts	1	18 9876 Scuttle seal	7.48	7.48T
950-075	1	Jaguar oil filter	9.40	9.40T
Subcontract		Rod's radiator/re-core radiator MX core	240.00	240.00
Parts	4	CO8949 trailing arm bush	5.27	21.08T
Parts	4	CO10995 panhard bush	1.75	7.00T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



<b>Bill To</b>
Kevin Kay



<b>Project</b>
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
Parts	8	CO8975 radiator mount	0.88	7.04T
Parts	2	144408M rear shock	83.00	166.00T
CAS GTX 20-50	9	Castrol GTX 20-50 Motor Oil Quart	4.59	41.31T
Parts	2	12-7995 rear axle shaft	287.54	575.08T
377-360	2	Fuel pump mount	4.25	8.50T
Subcontract		Gear Connection/rebuild rear axle	575.42	575.42
Subcontract		Power Draulics Inc. Hose Fitting	48.25	48.25
CAS HYPOY C G...	2	Castrol Hypoid GL5 Gear Oil Quart	6.05	12.10T
P10-3	4	3/8 x 24 unf male with lead .812" overall	2.30	9.20T
C344	2	Bullet connector	0.15	0.30T
C311	1	Bullet connector	1.29	1.29T
C222	2	1/4 spade cover	0.15	0.30T
CAS HD ANTI-F...	1	Castol Anti-Freeze Gallon	12.95	12.95T
CO179	1	Plug Spanner	39.20	39.20T
17-0125L	1	Tommy bar	11.34	11.34T
378-320	2	HD6 jet assy	15.71	31.42T
Subcontract		WVI/rebuild speedo	105.00	105.00
Subcontract		NCCS/rebuild generator, rebuild regulator	290.00	290.00

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



Bill To
Kevin Kay



Project
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
378-320	2	HD6 jet assy	20.95	41.90T
031-994	2	HD jet spring	1.85	3.70T
696-010	4	Carb gasket	1.00	4.00T
370-650	4	Fiber washer	1.10	4.40T
803-230	4	Door handle pin	1.20	4.80T
529-213	1	Jaguar cam cover gasket	8.95	8.95T
529-214	1	Jaguar cam cover gasket	8.95	8.95T
SCS	1	Sport coil sticker	19.99	19.99T
27556	1	Overflow hose 3/8	8.08	8.08T
713080	11	Chrome lock strip/per foot	1.25	13.75T
690559	22	Washer 17/64 x 9/16 20 SWG soft AL	0.18	3.96T
409-026	2	Dynamat	114.95	229.90T
950-075	1	Jaguar oil filter	9.80	9.80T
Parts	1	64068590 brake master cylinder	110.22	110.22T
Parts	2	CAC9937 Ball Joint, Lower	20.97	41.94T
Parts	1	011-935 Ball Joint, Pair, Upper	45.47	45.47T
Parts	4	14-2006 A-Arm Bushing	2.48	9.92T
Parts	4	GR 64932063 Wheel Cylinder	134.95	539.80T
Parts	8	06-3090 Caliper Bolt	1.83	14.64T
Parts	4	C8672 Bush, Upper A Arm	2.07	8.28T
D52D	1	Brake pads DB4 repco deluxe.	36.95	36.95T
Parts	2	CO 15350 Front Hub Seal	4.66	9.32T

<b>Total</b>
--------------

# Invoice

Date	Invoice #
8/13/2008	5330

## KEVIN KAY RESTORATIONS


1530 CHARLES DRIVE  
REDDING, CA 96003

Phone 530-241-8337

Fax 530-241-8339

kevinkay@pacbell.net

kevinkayrestorations.net



Bill To
Kevin Kay



Project
1962 Jaguar 3.8 MK II

Item	Qty.	Description	Rate	Amount
Parts	2	06 0770 Brake Hose	18.48	36.96T
Parts	1	CO27306 vacuum check valve	22.50	22.50T
Parts	6	Braided vacuum line	5.00	30.00T
Subcontract		PBE/rebuild brake booster	281.75	281.75
		CA SALES TAX	7.25%	531.70

<b>Total</b>	<b>\$9,541.99</b>
--------------	-------------------